

Handyperson Group

The Handyperson Group's Report to the Parish Council for November:

- Recreation Ground Trees inspected at 2 week intervals and after any particular stormy weather. All doing well but expert guidance needed on whether to slacked off tree ties.
- Speed Monitor maintained by changing batteries when necessary and cleaning the face.
- Leaf sweeping along the School perimeter footpath.
- Checked the non-slip surfaces on play equipment. Remains in good condition and re-coating not necessary yet. Will check again after school holiday period.
- New tasking of checking bolt plugs and covers on the play equipment. Several plugs found to be missing but replacement should wait for good weather when bolt recesses have dried out.

December/January tasks will be continued monitoring and maintenance.

Recommendation: 2.5 litres of Ronseal 10 Year Woodstain in Natural Oak to re coat the picnic tables outside St Marks and some benches in the Recreation Ground.