

Annual Play Area Inspection 2023 – Proposed Actions – PC Meeting 6 June 2023 Agenda Item 8.5

Equipment	Issue	Proposed Action	Action By
Bench without back			
Finding 1 (p25)	Rotten timber	Replace all affected timbers	Contractor
Multi Play (Junior)			
Finding 1 (p26)	Method of isolation	N/A (bridge already replaced)	N/A
Finding 6 (p29)	Worn/damaged rope bridge	N/A (bridge already replaced)	N/A
Finding 7 (p29)	Missing bolt cap covers	Replace missing covers	Handyperson
Finding 23 (p38)	Timber supports have rotted	Replace all affected timbers	Contractor
Finding 24 (p39)	Timber supports have rotted	Replace all affected timbers	Contractor
Finding 25 (p40)	Protective padding is coming loose	Resecure protective cladding	Contractor
Finding 26 (p41)	Missing rubber safety surfacing	Reinstate area of surfacing	Contractor
Multi Play (Junior)			
Finding 10 (p64)	Missing bolt cap covers	Replace missing bolt cap covers	Handyperson
Finding 16 (p67)	Chain wear/deterioration	Monitor chain and report when 40% worn	Handyperson
Swings - 1 Bay 2 Seat (Flat)			
Finding 2 (p68)	Reinstate safety surface	Replace rubber safety surfacing	Contractor
Finding 3 (p68)	Safety surfacing severely damaged	Replace rubber safety surfacing	Contractor
Finding 5 (p69)	Loose nuts to swing seats	Tighten loose swing seat connectors	Handyperson
Finding 6 (p70)	Chain wear/deterioration	Monitor chain and report when 40% worn	Handyperson
Swings - Basket Swing - Type 1			
Finding 1 (p71)	Grass mats silted up and the soil compacted	Replace rubber safety surfacing	Contractor
Finding 2 (p71)	Weed / vegetation growth	Replace rubber safety surfacing	Contractor
Finding 3 (p72)	Secure/reinstate safety surfacing	Replace rubber safety surfacing	Contractor
Finding 4 (p72)	Damaged areas of surfacing	Replace rubber safety surfacing	Contractor
Finding 5 (p73)	Ropes/nets are worn/damaged	Replace basket swing	Contractor
Finding 6 (p73)	Ropes/nets are worn/damaged	Replace basket swing	Contractor
Finding 9 (p75)	Chain wear/deterioration	Replace basket swing	Contractor
Swings - 1 Bay 2 Seat (Cradle)			
Finding 3 (p77)	One seat badly worn/damaged	Replace damaged cradle seat	Contractor

Multi Use Games Area – MUGA			
Finding 3 (p81)	String / tape on the ring	Replace basketball ring	Contractor
Finding 4 (p82)	Severely damaged backboard	Replace basketball backboard	Contractor
Finding 5 (p82)	Loose fence fixings	Secure fixings	Contractor
Finding 9 (p84)	Missing fence fixings	Replace fixings	Contractor